Hidden Splendor Resources Horizon Mine 57 West 200 South - Suite 400, Salt Lake City, Utah 84101

COOTOOZO Incoming

Cc: Amenda

RECEIVED

OK

DEC **2 0** 2013

DIV. OF OIL, GAS & MINING

December 18, 2013

Mr. Mike Herkimer Utah Department of Environmental Quality Division of Water Quality P.O. Box 144870 Salt Lake City, Utah 84114-4870

Dear Mr. Herkimer:

Hidden Splendor Resources respectfully submits the November 2013 – Discharge Monitoring Reports (DMRs) associated with the Horizon Mine UPDES Permit UTG040019.

If you have any questions, please feel free to call me at 435-636-0820.

Sincerely,

Kit Pappas

Hot lapper

NATIONAL POLLUTANT DISCHARGE ELIMINATATION SYSTEM (NPDES)

DISCHARGE MONITORING REPORT (DMR)

Form approved.

OMB No. 2040=00004

HIDDEN SPLENDOR RESOURCES, INC.

ADDRESS

NAME

3266 S. 125 WEST PRICE, UTAH 84501

FACILITY LOCATION

EPA Form 3320-1

HORIZON MINE

UTG040019
PERMIT NUMBER

001A DISCHARGE NUMBER

			MONITO	ORING PERIO	D		
	YEAR	МО	DAY		YEAR	мо	DAY
ROM	13	11	01	то	13	11	30

X Check here if No Discharge

NOTE: Read Instructions before completing this form

PARAMETER		a	UANTITY OR LOADING		QUA	LITY OF CO	NCENTRATI	ON	NO.	FREQUENCY OF			
		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE		UNITS	EX	ANALYSIS	SAM	PLE TY	PE.
Flow Rate	SAMPLE MEASUREMENT				N/A	N/A	N/A	****	0	MONTHLY		N/A	
00056 1 0 0 Effluent Gross Value	PERMIT REQUIREMENT	REPORT 30DA AVG	REPORT DAILY MX	(03) GPD	*****	*****	*****	****	INIA	1/31	м	EASRD	
рН	SAMPLE MEASUREMENT	****	****		N/A	N <u>/A</u>			NA				
00400 1 0 0 Effluent Gross Value	PERMIT REQUIREMENT	*****	*****	****	6.5 CAILY AIN	A	MA AUI	(12) .U	N/A	1/31		GRAB	
Solids, Total Suspended	SAMPLE MEASUREMENT	****	****		N/	J/A	A	(19)	IV/A				
00530 1 0 0 Effluent Gross Value	PERMIT REQUIREMENT	*****		****	***	35 A AVG	DAILY MAX	MG/L	N/A	1/31		GRAB	
Oil & Grease	SAMPLE MEASUREMENT		** **	.71	N/	N/A	N/A	(19)	N/A				
03582 1 0 0 Effluent Gross Value	PERMIT REQUIREMENT	** **		****	****	****	10 DAILY MAX	(19) MG/L	N/A	1/31		GRAB	
Iron, Total (as Fe)	SAMPLE MEASUREMENT		****		N/A	N/A	N/A	(19)	N/A				
01045 1 0 0 Effluent Gross Value	PERMIT REQUIREMENT	*****	*****	****	****	****	1.0 DAILY MAX	MG/L	N/A	1/31		GRAB	
Solids, Total Dissolved	SAMPLE MEASUREMENT	****		(26)	N/A	N/A	N/A		N/A				
70295 1 0 0 Effluent Gross Value	PERMIT REQUIREMENT	*****	2000 DAILY MAX	LBS/DY	****	****	*****	****	N/A	1/31		GRAB	
Floating solids or visible foam- visual	SAMPLE MEASUREMENT	****			N/A	N/A	N/A		N/A				
45613 1 0 Effluent Gross Value	PERMIT REQUIREMENT	*****	0 daily mx	***** Y=1, N=0	*****	*****	A		N/A	1/31	~	/ISUAL	
NAME/TITLE PRINCIPAL EXEC	01112 01110211	UNDER MY DIRECTION OR SU QUALIFIED PERSONNEL PRO	OF LAW THAT THIS DOCUMENT AND JPERVISION IN ACCORDANCE WITH . PERLY GATHER AND EVALUATE THE	A SYSTEM DESIGNED TO A	ASSURE THAT		_			TELEPHONE		DATE	
KIT PAPPAS/EN\	√.MGR.	RESPONSIBLE FOR GATHERI MY KNOWLEDGE AND BELIE SIGNIFICANT PENALTIES FOR	OR PERSONS WHO MANAGE THE S NG THE INFORMATION, THE INFORM EF, TRUE, ACCURATE, AND COMPL R SUBMITTING FALSE INFORMATION	NATION SUBMITTED IS, TO LETE. I AM AWARE THAT I, INCLUDING THE POSSIB	THE BEST OF THERE ARE	IGNATURE OF	PRINCIPAL EXE	CUTIVE	435	636-0820	13	12	18
TYPED OR PRINT			OWING VIOLATIONS, U.S.C. § 1001 At 10,000 and or maximum imprisonment of t			OFFICER OR	AUTHORIZED A	GENT	CODE	NUMBER	YEAR	мо	DAY

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

See permit for Settleable Solids Conditions, otherwise enter "N/A". If a visual sheen is observed then aoil and grease must be collected immediately.

2

NATIONAL POLLUTANT DISCHARGE ELIMINATATION SYSTEM (NPDES)

DISCHARGE MONITORING REPORT (DMR)

Form approved.

OMB No. 2040=00004

NAME

HIDDEN SPLENDOR RESOURCES, INC.

ADDRESS

3266 S. 125 WEST

PRICE, UTAH 84501

UTG040019 PERMIT NUMBER 002A
DISCHARGE NUMBER

MO

11

DAY

30

YEAR

13

FACILITY LOCATION **HORIZON MINE**

 MONITORING PERIOD

 YEAR
 MO
 DAY

 ROM
 13
 11
 01
 TO

X Check here if No Discharge

NOTE: Read Instructions before completing this form

PARAMETER		Q	UANTITY OR LOADING		QUA	LITY OF CO	NCENTRATI	ON	NO.	FREQUENCY OF			
		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	EX	ANALYSIS	SAMF	PLE TY	٦E
Flow Rate	SAMPLE MEASUREMENT			(03)	N/A	N/A	N/A	****	0	MONTHLY		N/A	
00056 1 0 0 Effluent Gross Value	PERMIT REQUIREMENT	REPORT 30DA AVG	REPORT DAILY MX	GPD	*****	****	****	*****	IN/A	1/31	ME	EASRD	
pH	SAMPLE MEASUREMENT	****	****		N/A	N/A			МА				
00400 1 0 0 Effluent Gross Value	PERMIT REQUIREMENT	*****	*****	****	6.5 DAILY VIN	1-:7	MASSIUI	(12) U	N/A	1/31	(GRAB	
Solids, Total Suspended	SAMPLE MEASUREMENT	****	****		N/	IJΔ	A	(19)	IV/A				
00530 1 0 0 Effluent Gross Value	PERMIT REQUIREMENT			****	44.	35 AAVC	DAILY MAX	MG/L	N/A	1/31	(GRAB	
Oil & Grease	SAMPLE MEASUREMENT	** **	** **		N/A	N/A	N/A	(19)	N/A				
03582 1 0 0 Effluent Gross Value	PERMIT REQUIREMENT	* <u>*</u>	** **		*****	****	10 DAILY MAX	MG/L	N/A	1/31	C	SRAB	
Iron, Total (as Fe)	SAMPLE MEASUREMENT	V	****	****	N/A	N/A	N/A	(19)	N/A				
01045 1 0 0 Effluent Gross Value	PERMIT REQUIREMENT	****	****	****	*****	*****	1.0 DAILY MAX	MG/L	N/A	1/31	C	SRAB	
Solids, Total Dissolved	SAMPLE MEASUREMENT	****		(26)	N/A	N/A	N/A	****	N/A				
70295 1 0 0 Effluent Gross Value	PERMIT REQUIREMENT	*****	2000 DAILY MAX	LBS/DY	*****	*****	****	****	N/A	1/31	C	SRAB_	
Floating solids or visible foam- visual	SAMPLE MEASUREMENT	****		****	N/A	N/A	N/A		N/A				
45613 1 0 Effluent Gross Value	PERMIT REQUIREMENT	****	0 daily mx	Y=1, N=0	***** *****	****	A *****		N/A	1/31		ISUAL	
NAME/TITLE PRINCIPAL EXEC		UNDER MY DIRECTION OR SL	OF LAW THAT THIS DOCUMENT AND IPERVISION IN ACCORDANCE WITH PERLY GATHER AND EVALUATE THI	A SYSTEM DESIGNED TO	ASSURE THAT		/_			ELEPHONE		DATE	
KIT PAPPAS/EN	/ MCD	MY INQUIRY OF THE PERSON RESPONSIBLE FOR GATHERII MY KNOWLEDGE AND BELIE	OR PERSONS WHO MANAGE THE S NG THE INFORMATION, THE INFORM EF, TRUE, ACCURATE, AND COMP	SYSTEM, OR THOSE PERSO MATION SUBMITTED IS, TO LETE. I AM AWARE THA'	ONS DIRECTLY THE BEST OF T THERE ARE	SIGNATURE OF	PRINCIPAL EXE	CUTIVE	435	636-0820	13	12	18
TYPED OR PRINT	TED	AND IMPRISONMENT FOR KN	R SUBMITTING FALSE INFORMATION OWING VIOLATIONS, U.S.C. § 1001 A	ND 33 U.S.C. § 1319. (Penal		OFFICER OR	AUTHORIZED A	GENT	AREA CODE	NUMBER	YEAR	мо	DAY

EPA Form 3320-1

PERMITTEE NAME/ADDRESS (include Facility Name/Location if Different)

NATIONAL POLLUTANT DISCHARGE ELIMINATATION SYSTEM (NPDES)

2

2 0F

Form approved.

NAME

HIDDEN SPLENDOR RESOURCES, INC.

DISCHARGE MONITORING REPORT (DMR)

OMB No. 2040=00004

ADDRESS

3266 S. 125 WEST PRICE, UTAH 84501

UTG040019

002A

PERMIT NUMBER

DISCHARGE NUMBER

FACILITY

HORIZON MINE

LOCATION

			MONITO	ORING PERIO	ID.		
	YEAR	мо	DAY		YEAR	мо	DAY
FROM	13	11	01	то	13	11	30

X Check here if No Discharge

NOTE: Read Instructions before completing this form

PAGE

PARAMETER		Q	UANTITY OR LOADING		QUA	LITY OF CO	NCENTRATI	NC	NO.	FREQUENCY OF		
		AVERAGE	MAXIMUM	UNITS	MINIMUM	AVERAGE	MAXIMUM	UNITS	EX	ANALYSIS	SAMF	LE TYPE
Solids, settleable	SAMPLE MEASUREMENT			(03)	N/A	N/A	N/A	****	N/A	N/A		N/A
00545 Q 0 See Comments	PERMIT REQUIREMENT	REPORT 30DA AVG	REPORT DAILY MX	GPD	*****	****	*****	****	N/A	1/30	VI	SUAL
Sanitary waste dischareged-as:	SAMPLE MEASUREMENT	****	****				7	(12)	N/A	N/A	ı	N/A
45614 1 0 Effluent Gross	PERMIT REQUIREMENT	*****	*****	*****	DAIL N V	***	DAI 71 X	SU	N/A	1/31	G	RAB
	. 1/		7151			, ,						
NAME/TITLE PRINCIPAL EXECT	UTIVE OFFICER	CERTIFY UNDER PENALTY COUNDER MY DIRECTION OR SL	DE LAW THAT THIS DOCUMENT AND PERVISION IN ACCORDANCE WITH	D ALL ATTACHMENTS WERE A SYSTEM DESIGNED TO AS	SSURE THAT	N-A	0		1	'ELEPHONE	D	ATE
NAME/TITLE PRINCIPAL EXECT	/.MGR.	CERTIFY UNDER PENALTY O UNDER MY DIRECTION OR SL JOUALIFIED PERSONNEL PROIS MY INQUIRY OF THE PERSON RESPONSIBLE FOR GATHERII MY KNOWLEGGE AND BELIE	OF LAW THAT THIS DOCUMENT AND	D ALL ATTACHMENTS WERE A SYSTEM DESIGNED TO AS EINFORMATION SUBMITTEL SYSTEM, OR THOSE PERSON AATION SUBMITTED IS, TO T LETE. I AM AWARE THAT	SSURE THAT D. BASED ON NS DIRECTLY THE BEST OF THERE ARE		PRINCIPAL EXE	CUTIVE	1 435	ELEPHONE 636-0820	13	ATE

COMMENTS AND EXPLANATION OF ANY VIOLATIONS (Reference all attachments here)

See permit for Settleable Solids Conditions, otherwise enter "N/A". If a visual sheen is observed then aoil and grease must be collected immediately.